



Visual Consulting
Visual Property Assessments



[About Us](#) :: [Services](#) :: [Structural Failure Photos](#) :: [Project Request Form](#) :: [Home](#)

Office (843) 308-0600
Fax (843) 747-8167

Examples of safety issues and structural damage found through destructive testing methods, along with examples of corrective measures.



Scott Dow
Cell (843) 364-6711



Flashing



Flashing



George Thames
Cell (843) 518-2634



Wiring



Flashing



Improper Cleaning for Asbestos



Moisture Meter Testing




Bracing



Bracing and Blocking



Framing



Power Line



Connections and Modifications



Electrical Box



Flashing Technique



Settling and Water Intrusion



Roof Membrane Failure



Improper Flashing & No Drain Pan Under Door



Mold From Crawl Space



Missing Roof Vent Allows Water Intrusion

[VIEW MORE REPAIR PHOTOS>>](#)

[About Us](#) :: [Services](#) :: [Structural Failure Photos](#) :: [Project Request Form](#) :: [Home](#)

Visual Consulting, LLC, was organized in 2002 by Scott Dow, President of Dow, Inc., a leader and expert in commercial, multi-family, residential construction, and historic renovation services in Charleston, South Carolina, since 1987.

Office: 843-308-0600

Scott Dow (Cell) 843-364-6711 George Thames (Cell) 843-518-2634
Visual Consulting, LLC ~ P.O. Box 727 ~ Mt. Pleasant, SC 29465